



**Firmware Version:** 1.11r001  
**Published:** March 09, 2021

**Content:**

Revision History and System Requirement:.....2

New Features: .....2

Problems Fixed: .....2

Known Issues: .....2

Related Documentation:.....3

## Revision History and System Requirement:

FW Version	Date	Model	HW	Remark
1.11r001	09-Mar.-2021	DAP-3711	A1	1st release

## New Features:

Firmware Version	New Features
1.11r001	Initial release

## Problems Fixed:

Firmware Version	Problems Fixed
1.11r001	Initial release

## Known Issues:

Firmware Version	Issues
1.11r001	<p>DAP-3711 is a point-to-point device, and the following known problems will occur in AP mode.</p> <ol style="list-style-type: none"> <li>1. The IP address of the connected station always displays 0.0.0.0 if client is not the same device.</li> <li>2. When AP LAN Port set to DHCP client, AP did not immediately re-initial DHCP.</li> <li>3. Roaming function is not supported when running in AP mode.</li> <li>4. DAP-3711 LAN Port does not support multiple VLAN ID.</li> </ol>

**Related Documentation:**

---

- DAP-3711\_A1\_Manual\_v1.00(WW)
- DAP-3711\_A1\_QIG\_v1.10(WW)