



Firmware Version: 1.18r001
Boot Code Version: 1.00
Published: Apr. 09, 2021

Content:

Revision History and System Requirement: 2
New Features: 2
Problem Fixed: 2
Known Issues: 2
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version	Remark
V1.18r001	9-Apr.-2020	DAP-3712	A1	1st release

New Features:

Firmware Version	New Features
V1.18r001	First release

Problem Fixed:

Firmware Version	Problems Fixed
V1.18r001	1. First Release

* D-Link tracking number is enclosed in ()

Known Issues:

Firmware Version	Issues	Workaround
V1.18r001	<p>DAP-3712 is a point-to-point device, and the following known problems will occur in AP mode.</p> <ol style="list-style-type: none"> The IP address of the connected station always displays 0.0.0.0 if client is not the same device. 	

2. When AP LAN Port set to DHCP client, AP did not immediately re-init DHCP
3. Roaming function is not supported when running in AP mode.
4. DAP-3712 LAN Port does not support multiple VLAN ID

Related Documentation:

- [DAP-3712_A1_Manual_V1.00\(WW\)](#)
- [DAP-3712_A1_QIG_V1.00\(WW\)](#)