



Firmware Version: 1.00r010

Published Date: 2021/Mar/30

Content:

Upgrading Instructions: 2

 Upgrading by using Web-UI..... 2

New Features:..... 2

Changes of MIB & D-View Module: 2

Problems Fixed: 2

Known Issues: 3

Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.00r010	2021/Mar/30	DIS-2650AP	A1

Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address setting is dynamic ip, and you can enter <http://dis2650ap.local> to login, if it cannot get ip address from DHCP server, it's ip address will back to 192.168.0.50.
3. Enter administrator's username and password, user name and password is "admin" by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

1. First release

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
------------------	----------------

N/A	None
-----	------

Known Issues:

Firmware Version	Known Issues
1.00r010	<ol style="list-style-type: none"> 1. The Auto 5GHz channel jumped to the wrong channel after changing the operation mode to WDS mode or WDS with AP mode. 2. WDS information takes too long to detect disconnection.

Related Documentation:

None