D-Link®
BUILDING NETWORKS FOR PEOPLE

DIR-457 Firmware Release Note.

Firmware: v1.03B03

Hardware: A1

Date: 2010/10/21

Problems Resolved:

1. [GMP issue] solved

2. [WEB GUI connect/disconnect button] solve the issue in WAN manual mode

3. [MAC filter] modified

4. [DHCP client] modified

5. [WEB GUI no reboot after finishing internet wizard] solved

6. [LAN Setup] solved

7. [Security] The incorrect security on WEB GUI after finishing WPS is solved

8. [Specific symbols for SSID setting] solved and can be saved

9. [Specific symbols for Password] solved

10. [Login session function abnormal] solved

Enhancement:

1. Add new DLA APN profile

2. Add Pin lock mechanism

Known Issues:

1. [ConnMgr] Wireless SSID doesn't support some symbol

2. [SIP] SIP ALG function fail

3. [DHCP] DHCP Client entry must disappear when expired time is time out

4. [WAN] The number of Ip Conntrack can't reduce after BT Test

5. [WLAN] WAN IP still exist from CLI after Connect-on demand time out.

6. [Samba] Field checking fail for Server name

7. [Evaluation]Device randomly goes into power down condition and fails to reboot after SW factory rest

8. [3G settings for Manual config] When the SIM card is removed, the country and ISP value should be blank.

9. [SMB] multiple files get and put is very slow

10. [Samba] In Windows 7, when using the correct account and password it will enter the public directory.