



DAP-1360 Firmware Hotfix Release Notes

Firmware: 6.15EUB01

Hardware: F2

Date: 1/17/2023

3rd Party Report:

Trend Micro's Zero Day Initiative

Problems Resolved:

webproc var:menu Stack-based Buffer Overflow Remote Code Execution Vulnerability

webproc WEB_DisplayPage Directory Traversal Information Disclosure Vulnerability

webproc Heap-based Buffer Overflow Remote Code Execution Vulnerability

webproc Stack-based Buffer Overflow Remote Code Execution Vulnerability

webproc var:sys_Token Heap-based Buffer Overflow Remote Code Execution Vulnerability

webproc WEB_DisplayPage Stack-based Buffer Overflow Remote Code Execution Vulnerability

webproc var:page Stack-based Buffer Overflow Remote Code Execution Vulnerability

webupg UPGCGI_CheckAuth Numeric Truncation Remote Code Execution Vulnerability

webproc COMM_MakeCustomMsg Stack-based Buffer Overflow Remote Code Execution Vulnerability

Hardcoded Credentials Authentication Bypass Vulnerability

Multiple Parameters Stack-Based Buffer Overflow Remote Code Execution Vulnerability



DISCLAIMER: Please note that this is a device beta software, beta firmware, or hot-fix release which is still undergoing final testing before its official release. The beta software, beta firmware, or hot-fix is provided on an “as is” and “as available” basis and the user assumes all risk and liability for use thereof. D-Link does not provide any warranties, whether express or implied, as to the suitability or usability of the beta firmware. D-Link will not be liable for any loss, whether such loss is direct, indirect, special or consequential, suffered by any party as a result of their use of the beta firmware.