

**Model Name: DBR-330 A1****Firmware Version: 1.01.01****Published Date: 12.30, 2025**

Copyright © 2025

Copyright Notice

This publication, including all photographs, illustrations and software, is protected under international copyright laws, with all rights reserved. Neither this manual, nor any of the material contained herein, may be reproduced without written consent of the author.

Disclaimer

The information in this document is subject to change without notice. The manufacturer makes no representations or warranties with respect to the contents hereof and specifically disclaim any implied warranties of merchantability or fitness for any particular purpose. The manufacturer reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of the manufacturer to notify any person of such revision or changes.

Limitations of Liability

UNDER NO CIRCUMSTANCES SHALL D-LINK OR ITS SUPPLIERS BE LIABLE FOR DAMAGES OF ANY CHARACTER (E.G. DAMAGES FOR LOSS OF PROFIT, SOFTWARE RESTORATION, WORK STOPPAGE, LOSS OF SAVED DATA OR ANY OTHER COMMERCIAL DAMAGES OR LOSSES) RESULTING FROM THE APPLICATION OR IMPROPER USE OF THE D-LINK PRODUCT OR FAILURE OF THE PRODUCT, EVEN IF D-LINK IS INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. FURTHERMORE, D-LINK WILL NOT BE LIABLE FOR THIRD-PARTY CLAIMS AGAINST CUSTOMER FOR LOSSES OR DAMAGES. D-LINK WILL IN NO EVENT BE LIABLE FOR ANY DAMAGES IN EXCESS OF THE AMOUNT D-LINK RECEIVED FROM THE END-USER FOR THE PRODUCT.



Firmware Release Note

Table of Content:

Revision History and System Requirement: 3

Upgrading Instructions: 3

New Features: 3

Problem Fixed: 3

Known Issues:..... 4



Firmware Release Note

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
1.01.01	12/30/2025	DBR-330	A1

Upgrading Instructions:

Please use Web GUI upgrade to firmware version v1.01.01 on DBR-330 device.

New Features:

Firmware Version	New Features
1.01.01	N/A

Problem Fixed:

Firmware Version	Problems Fixed
1.01.01	1. Fixed Auto-detection failure within the Wizard. 2. Removed Redundant warning messages in the Wizard



Firmware Release Note

Known Issues:

Firmware Version	Known Issues
1.01.01	1. PDF preview is currently unavailable within the app.