



Firmware Version: 2.56rc550

Published Date: 2011/11/04

Content:

Upgrading Instructions:.....	2
Upgrading by using Web-UI.....	2
New Features:.....	2
Changes of MIB & D-View Module:.....	2
Problems Fixed:	2
Known Issues:	3
Related Documentation:	3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
2.56rc550	2011/11/04	DWL-3200AP	B2


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

None

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V2.56rc550	1. Solve SSH issue.

Known Issues:

Firmware Version	Known Issues
V2.56rc550	None

Related Documentation:

None