

DUB-1312 Release Notes

Hardware: A1

CD Version: V4

Date: 2016/11/08

Windows 10 support, Performance enhancement, and bugs fix
MAC OS v10.12 Sierra support

Install software version

Windows : V 3.0.0.0

MAC : V 2.8.0

Linux : V 1.4.0

Detail Driver version

Windows

Win10/Win8 (x86/x64) : V 1.18.2.0

Win7_x86 : V 1.12.11.0

Win7_x64 : V 1.14.11.0

XP_Vista_x86 : V 1.4.2.0

XP_Vista_x64 : V 1.6.2.0

MAC

Mac 10.9~10.11: V 1.8.0

Mac 10.6~10.8: V 1.11.0

Known Issues:

None

Enhancements:

None

CD Version: V3

Date: 2015/12/

Add Win10 support & support MAC 10.11

Install software version

Windows : V 2.0.0.0

D-Link Corporation confidential



MAC : V 1.7.0
Linux : V 1.4.0

Detail Driver version

Windows

Win8_x86 : V 1.16.12.0
Win8_x64 : V 1.16.12.0
Win7_x86 : V 1.12.8.0
Win7_x64 : V 1.14.8.0
XP_Vista_x86 : V 1.4.2.0
XP_Vista_x64 : V 1.6.2.0

MAC

Mac ~10.8 : V 1.4.0
Mac 10.11 : V 1.7.0

Known Issues:

None

Enhancements:

None

CD Version: V2

Date: 2014/03/28

Add Win8 Driver & support MAC 10.9

Install software version

Windows : V 1.0.3.0
MAC : V 1.6.0
Linux : V 1.4.0

Detail Driver version

Windows

Win8_x86 : V 1.16.10.0
Win8_x64 : V 1.16.10.0
Win7_x86 : V 1.12.7.0
Win7_x64 : V 1.14.7.0
XP_Vista_x86 : V 1.4.1.0
XP_Vista_x64 : V 1.6.1.0



MAC

Mac ~10.8 : V 1.4.0

Mac 10.9 : V 1.5.0

Known Issues:

None

Enhancements:

None

CD Version: V1

Date: 2013/07/09

First Release

Install software version

Windows : V 1.0.0.0

MAC : V 1.4.0

Linux : V 1.4.0

Detail Driver version

Windows

Win7_x86 : V 1.12.7.0

Win7_x64 : V 1.14.7.0

XP_Vista_x86 : V 1.4.1.0

XP_Vista_x64 : V 1.6.1.0

MAC

Mac ~10.8 : V 1.4.0

Known Issues:

None

Enhancements:

None